

May 8, 2007

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Stop P1-137  
Washington, DC 20555-0001

ULNRC05412



Ladies and Gentlemen:

**DOCKET NUMBER 50-483  
CALLAWAY PLANT UNIT 1  
UNION ELECTRIC CO.  
FACILITY OPERATING LICENSE NPF-30  
LICENSEE EVENT REPORT 2007-002  
Manual Reactor Trip at Reduced Power due to Inadequate Feedwater Control**

The enclosed licensee event report is submitted in accordance with 10CFR50.73(a)(2)(iv)(A) to report a manual reactor trip and auxiliary feedwater actuation.

This letter does not contain new commitments.

Sincerely,

A handwritten signature in black ink, appearing to read "Fadi M. Diya".

Fadi M. Diya  
Director Plant Operations

FMD/CSP/slk  
Enclosure

IE22

ULNRC05412

May 8, 2007

Page 2

Mr. Bruce S. Mallett  
Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011-4005

Senior Resident Inspector  
Callaway Resident Office  
U.S. Nuclear Regulatory Commission  
8201 NRC Road  
Steedman, MO 65077

Mr. Jack N. Donohew (2 copies)  
Licensing Project Manager, Callaway Plant  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Mail Stop O-7D1  
Washington, DC 20555-2738

Missouri Public Service Commission  
Governor Office Building  
200 Madison Street  
PO Box 360  
Jefferson City, MO 65102-0360

Records Center  
Institute of Nuclear Power Operations  
700 Galleria Parkway  
Atlanta, GA 30339

ULNRC05412

May 8, 2007

Page 3

bcc: C. D. Naslund  
A. C. Heflin  
C. R. Younie  
D. T. Fitzgerald  
G. A. Hughes  
D. E. Shafer  
S. L. Gallagher (100)  
L. M. Belsky (NSRB)  
K. A. Mills  
P. M. Bell  
[msp@nrc.gov](mailto:msp@nrc.gov)  
[ded@nrc.gov](mailto:ded@nrc.gov)  
[LEREvents@inpo.org](mailto:LEREvents@inpo.org)  
[babrook@wcnoc.com](mailto:babrook@wcnoc.com)  
A160.0761

Certrec Corporation  
4200 South Hulen, Suite 422  
Fort Worth, TX 76109

*(Certrec receives ALL attachments  
as long as they are non-safeguards  
and public disclosed).*

Send the following without attachments:

Ms. Diane M. Hooper  
Supervisor, Licensing  
WCNOC  
P.O. Box 411  
Burlington, KS 66839

Mr. Scott Bauer  
Regulatory Affairs  
Palo Verde NGS  
P.O. Box 52034,  
Mail Station 7636  
Phoenix, AZ 85072-2034

Mr. Dennis Buschbaum  
TXU Power  
Comanche Peak SES  
P.O. Box 1002  
Glen Rose, TX 76043

Mr. Stan Ketelsen  
Manager, Regulatory Services  
Pacific Gas & Electric  
Mail Stop 104/5/536  
P.O. Box 56  
Avila Beach, CA 93424

## LICENSEE EVENT REPORT (LER)

(See reverse for required number of  
digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to [infocollects@nrc.gov](mailto:infocollects@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME Callaway Plant Unit 1	2. DOCKET NUMBER 05000483	3. PAGE 1 OF 4
---	------------------------------	-------------------

4. TITLE  
Manual Reactor Trip at Reduced Power Due to Inadequate Feedwater Control

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
03	09	2007	2007	- 002 -	00	05	08	2007	FACILITY NAME	DOCKET NUMBER

9. OPERATING MODE 1	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFRs: (Check all that apply)			
10. POWER LEVEL 30%	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A	

## 12. LICENSEE CONTACT FOR THIS LER

FACILITY NAME K.A. Mills, Supervising Engineer, Safety Analysis/Regional Regulatory Affairs	TELEPHONE NUMBER (Include Area Code) 573-676-4317
--	--

## 13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX
B	SJ	CPOS	B455	YES	B	AA	CON		YES

## 14. SUPPLEMENTAL REPORT EXPECTED

☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE)☒ NO

## 15. EXPECTED SUBMISSION DATE

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On March 9, 2007, while operating at 100 percent power, Callaway Plant experienced a main condenser tube leak. At 0824, high sodium levels were indicated in the main steam condenser, requiring power reduction to less than five percent power until all Action Levels for condenser sodium were exited. The on-shift Operations crew began reducing power to enter MODE 3 in accordance with procedural guidance. During the transition from the Main Feedwater Regulation Valves (MFRV) to the Main Feedwater Regulation Bypass Valves (MFRBV), problems were experienced controlling water level in the "C" steam generator (S/G). At 1043, with both the MFRV and MFRBV indicating closed and the "C" S/G level still increasing, the reactor was manually tripped. The level control problem was attributed to a failed I/P positioner on the MFRV. The controller was replaced with a like kind controller.

Digital rod position indication for control rod K10 failed during the event. The control rod was fully inserted. This failure was attributed to a bent connector pin in the digital rod position indication system. The connector pin was repaired and tested satisfactorily.

**LICENSEE EVENT REPORT (LER)**

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
Callaway Plant Unit 1	05000483	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 4
		2007	- 002	- 00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

**I. DESCRIPTION OF THE REPORTABLE EVENT**

**A. REPORTABLE EVENT CLASSIFICATION**

10CFR50.73(a)(2)(iv)(A) – Any event or condition that resulted in manual or automatic actuation of any of the systems listed in paragraph (a)(2)(iv)(B) of this section

- (1) Reactor protection system (RPS) including: reactor scram or reactor trip.
- (6) PWR auxiliary or emergency feedwater system.

**B. PLANT OPERATING CONDITIONS PRIOR TO THE EVENT**

MODE 1 at approximately 25-30 percent power with a rapid power reduction in progress due to a main condenser tube leak and subsequent high condenser sodium levels.

**C. STATUS OF STRUCTURES, SYSTEMS OR COMPONENTS THAT WERE INOPERABLE AT THE START OF THE EVENT AND THAT CONTRIBUTED TO THE EVENT**

Valve AEFCV0570, "C" Main Feedwater Regulating Bypass Valve (MFRBV) was isolated for scheduled maintenance when the event started.

**D. NARRATIVE SUMMARY OF THE EVENT, INCLUDING DATES AND APPROXIMATE TIMES**

On March 9, 2007, while operating at 100 percent power, Callaway Plant experienced a main condenser tube leak. At 0824, high sodium levels were indicated in the main steam condenser, requiring power reduction to less than five percent power until all Action Levels for condenser sodium were exited. The on-shift Operations crew began reducing power to enter MODE 3 in accordance with procedural guidance. During the transition from the Main Feedwater Regulation Valves (MFRV) to the Main Feedwater Regulation Bypass Valves (MFRBV), problems were experienced controlling water level in the "C" steam generator (S/G). At 1043, with both the MFRV and MFRBV indicating closed and the "C" S/G level still increasing, the reactor was manually tripped.

The "C" MFRBV was isolated for scheduled maintenance when the event started. Upon completion of the work, the valve was retested and returned to service at 0928 while the rapid power reduction was in progress.

The Balance of Plant (BOP) Operator reported the "C" MFRBV did not respond correctly during the transition from the MFRV to the MFRBV on the "C" steam generator. Indications were no change in feedwater flow was noted for corresponding change in valve demand in either open and closed directions. Feedwater flow changed to a value greater than expected causing steam generator level to rise outside the normal operating band. Feedwater flow to the "C" steam generator indicated about 1.3E6 lbs/hr and level in the "C" S/G continued to increase, while both the "C" MFRV and MFRBV indicated closed. The BOP Operator reported the condition and at 10:43 the Control Room Supervisor directed the Reactor Operator to trip the reactor due to loss of level control for "C" steam generator. (At this point it should be noted that the actual problem was a failed I/P positioner on MFRV

**LICENSEE EVENT REPORT (LER)**

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
Callaway Plant Unit 1	05000483	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 4
		2007	- 002	- 00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

AEFCV0530).

After the manual reactor trip all rods indicated fully inserted except for rod K10. The digital rod position indication (DRPI) for control rod K10 failed during the trip. Control rod K10 was believed to be fully inserted, but was treated as indeterminate. Rod K10 was assumed as not inserted when the shutdown margin calculation was performed and the plant conservatively implemented the actions of FSAR specification 16.1.3.1. Troubleshooting showed that the problem with was with the DRPI for control rod K10, therefore, all rods were fully inserted after the reactor trip.

**E. METHOD OF DISCOVERY OF EACH COMPONENT, SYSTEM FAILURE, OR PROCEDURAL ERROR**

During the power reduction, "C" S/G level was increasing with both the MFRV and MFRBV indicating closed. Subsequent investigation indicated that the positioner for the "C" MFRV had failed. A field walkdown of AEFCV0530, following the plant trip, identified that the positioner was exhibiting abnormal indications. Observation of the LCD display indicated that "ERROR 12" was being displayed on the positioner. The positioner was periodically reinitializing on approximately 5 second intervals. It was also identified that AEFCV0530 was off its closed seat as identified by a yellow positioning pin being approximately one inch above the close limit switch actuating arm.

The rod K10 DRPI malfunction was discovered after the reactor trip, when a general warning annunciator was received for the digital position rod indication for control rod K10.

**II. EVENT DRIVEN INFORMATION**

**A. SAFETY SYSTEMS THAT RESPONDED**

All safety systems functioned as designed with the exception of the digital rod position indication for control rod K10 which failed during the trip due to an existing problem. Control rod K10 was believed to be fully inserted, but was being treated as indeterminate. Main feedwater isolation and motor-driven auxiliary feedwater actuations occurred as expected. Both trains of the emergency diesel generators and the offsite power supplies were available.

**B. DURATION OF SAFETY SYSTEM INOPERABILITY**

Duration of the indication problem for control rod K10 was from the time of the reactor trip on March 9, 2007, through completion of post maintenance testing on the digital rod position system for control rod K10 on March 11, 2007. The duration was 1 day 13 hours.

The safety function for the MFRV and MFRBV is to close on a feedwater isolation signal. The safety function occurred when the reactor was tripped on March 9, 2007. There was not a safety system inoperability associated with the MFRV or MFRBV.

**C. SAFETY CONSEQUENCES AND IMPLICATIONS OF THE EVENT.**

**LICENSEE EVENT REPORT (LER)**

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
Callaway Plant Unit 1	05000483	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 4
		2007	- 002	- 00	

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

The "C" MFRV, AEFCV0530, was able to perform its nuclear safety function to close on a Feedwater Isolation Signal (FWIS) during this event because this safeguards signal bypasses the valve positioner. From a review of plant data after the reactor trip, the MFRV fully closed when the FWIS was generated.

This event was evaluated with the Callaway PRA model. The evaluation determined that the conditional core damage probability (CCDP) of the event was less than 1E-6; therefore, this event was of very low risk significance. Use of the PRA model to evaluate the event provides for a comprehensive, quantitative assessment of the potential safety consequences and implications of the event, including the consideration of alternative conditions beyond those analyzed in the FSAR.

**III. CAUSE(S) OF THE EVENT AND CORRECTIVE ACTION(S)**

During the downpower, at approximately 30% power, the positioner to AEFCV0530, "C" SG MFRV, failed such that the valve would not change position on demand. The programmed failure response is 'Fail as is'. This is supported by the fact that the feedwater flow could not be reduced below 1.3E6 lbs/hr. An as-found AOV Diagnostic test was performed that determined the positioner had failed. The positioner could be made to intermittently operate by lightly tapping on it. The positioner was sent to an independent laboratory for analysis. The root cause of the event was attributed to a defective or damaged feedback shaft gear tooth in the positioner. The gear tooth damage was most likely due to a manufacturing defect or a problem during the initial factory assembly of the positioner.

The positioner has been replaced with a like kind positioner. The functionality and operability of the MFRV were verified through the performance of diagnostic and surveillance testing prior to returning the unit to service. An extent of condition review has been completed with no additional deficiencies identified.

The cause of the digital rod position indication problem for control rod K10 was a bent pin on a cable connector. The bent pin was straightened. Post maintenance testing was completed satisfactorily.

**IV. PREVIOUS SIMILAR EVENTS**

A reactor trip due to a MFRV positioner failure is not a recurrence for Callaway.

**V. ADDITIONAL INFORMATION**

The system and component codes listed below are from the IEEE Standard 805-1984 and IEEE Standard 803A-1984 respectively.

AEFCV0530, Steam Generator C Main Feedwater Regulating Valve, IEEE System: SJ, Feedwater Component: FCV, Valve, Control, Flow

Positioner on AEFCV00530, System: SJ, Feedwater, Component: CPOS, positioner Manufacturer: ABB, Model: TZID-C

Digital Rod Position Indication, System: AA, Control Rod Drive Component: CON, connector